The following site is being submitted for inclusion into the Groundwater GIS registry:

For DNR County and Region list go to:
 g:\pf\pecfa\site\gis\BRRTS County and Region Codes.xls

- To begin, click on cell to the right of; This is a:
- Use Tab, ↓ or Pg Down to navigate form. Print & include with file when completed.

	This is a:	New Submittal					
	BRRTS ID (no dashes):	0341177877					
	Comm # (no dashes):	53205239918					
	County:	Milwaukee					
	Region:	Southeast					
	Site name:	Jaeger Bakery					
	Street Address:	918 W Somers St					
	City:	Milwaukee					
	Final Closure Date	2001-01-10					
	Closure Conditions:	met					
	Off-source property contamination?	No					
(If yes,	attach locational data and deed information on pg. 2)						
	Right-of-way contamination?	No					
	Contaminated media:	Groundwater					
GPS Coordinates (meters in the WTM91 projection)							
	Easting (X):	689157					
	Northing (Y):	288481					
	Collection Method:	DNR Web Site					
	Scale or Resolution:	1:3,839					
(1:24,00	00 scale or finer)						
	Prepared by:	Stephen Mueller					
	Submitted by:	Cheryl Nelson					
0							
Source	Property Checklist						
\boxtimes	— Ty - The transfer of the tra						
_	NR 140 ES						
	Where the legal description in the deed(s) refers to a certified survey map or recorded plat map, include those documents						
\boxtimes	Parcel ID for all properties w/ GW > NR 140 ES						
\boxtimes	General Location Map						
\boxtimes	Detailed Location Map showing property boundaries, buildings, MW(s) and/or potable wells						
_	etc for properties with GW >NR140 ES						
	Latest Map(s) showing extent or outline of current GW plume (isoconcentrations)						
	Map showing GW flow direction						
\boxtimes	Latest Table of GW results						
	Geologic cross section (if generated as part of the						
	Statement signed by RP certifying correctness of legal descriptions Updated Database						



ENVIRONMENTAL & REGULATORY SERVICES
101 West Pleasant Street, Suite 205
Milwaukee, Wisconsin 53212
Fax (414) 220-5374
TDD# (608) 264-8777
www.commerce.state.wi.us
Tommy G. Thompson, Governor
Brenda J. Blanchard, Secretary

January 10, 2001

Metz Baking Co. Attn: Ms. Theresa Lanctot 8400 Maryland Ave. St. Louis, MO 63105 Philip Service Corp. Attn: Mr. Eric Page 210 W. Sand Bank Road Columbia IL 62236

RE:

Commerce# 53205-2399-18A, BRRTS# 03-41-177877

Jaeger Bakery, 918 West Somers Street, Milwaukee, WI 53205

10,000-gallon diesel fuel UST (reg. #300956) removed on Nov. 4, 1997.

Case Closure

Dear Ms. Lanctot:

On behalf of the Department of Commerce, I have reviewed the subject case for closure. Based on the information provided, it appears that petroleum contamination identified in site soil has been investigated in compliance with the requirements of Wis. Adm. Code (WAC) chs. NR 700-750. It is understood that residual petroleum contamination remains in soil beneath the former diesel fuel UST bed at the subject property. However, using the standards established in ch. NR 700, and the risk criteria of WAC ch. Comm 46, the Department has determined that the diesel fuel UST site does not pose a significant threat to the environment and human health. Therefore, the Department considers the diesel fuel UST case closed, having determined that no further investigation or remedial action is necessary. In making this determination, I reviewed the following case documents:

- Closure Assessment for Underground Storage Tank, Summit Envirosolutions, Apr. 1, 1998.
- Subsurface Investigation Report, Summit Envirosolutions, Jul. 7, 1999.
- Groundwater Monitoring Report, Summit Envirosolutions, Jun. 5, 2000.
- Case Summary and Closeout Request, Summit Envirosolutions, Jun. 9, 2000.
- Miscellaneous letters and regulatory tracking documents in case file.

Residual petroleum contamination concentrations that exceed the interim guidance (Publ. RR-519-97) Table 1 levels for benzo(a)pyrene and phenanthrene remain present at depth near the former diesel fuel UST location. However, the concentrations were in saturated soil beneath the groundwater table, and no petroleum analytes were detected in a groundwater sample from beneath the former tank bed.

In the event that any of the remaining petroleum contamination is uncovered in the future, it will be the responsibility of the property owner to properly handle and dispose of all contaminated soil and groundwater that does not meet applicable State and Federal standards. Furthermore, if future site conditions indicate that any remaining contamination poses a threat, the need for

Commerce# 53205-2399-18A, BRRTS# 03-41-177877

Jaeger Bakery 918 West Somers Street, Milwaukee, WI 53205 January 10, 2001

Page 2

further remediation would be determined and required if necessary. If subsequent information indicates a need to reopen this case, the original claim under the PECFA fund would also be reopened and you could apply for assistance to the extent of remaining eligibility.

Thank you for your efforts in protecting and restoring the environment. If you have any questions, please contact me at the letterhead address, or at (414) 220-5402 or smueller@commerce.state.wi.us.

Sincerely,

Stephen D. Mueller Hydrogeologist

PECFA Site Review Section

C: case file

Document Number

NOTICE OF CONTAMINATION TO PROPERTY

Legal Description of the Property: In re:

(as it appears on the most recent deed)
LEGALS ORGINAL PLAT OF THE TOWN OF MILW WEST OF
THE RIVER IN DESCRIPTION SECS (20 & 29)-7-22
BLOCK 106 LOTS 7 THRU 21 & ALL VAC ALLEYS ADJ &
VAC ST ADJ LOTS 8 & 9 ON E & ALL VAC W PLYMOUTH
AV IN SD BLK 106 & N 1/2 VAC W SOMERS ST ADJ BLK
106 ON S & ELY 1/2 VAC N 10TH ST ADJ BLK 106 ON
W EXC THAT PART VAC N 10TH ST LYING N OF CL VAC
W CHERRY ST EXTD

8310386

REGISTER'S OFFICE | SS Milwaukee County, WI) RECORDED AT 11:52 AM 07-09-2002

IGNATIAS J. NIEMCZYK REGISTER OF DEEDS

AMOUNT 23,00

Recording Area

Name and Return Address

ENVIRONMENTAL ASSOCIATES, IN 210 GREEN BAY ROAD THIENSVILLE, WI 53092

361-1179-116-8
Parcel Identification Number (PIN)

STATE OF WISCONSIN) ss COUNTY OF MILWAUKEE)

METZ BAKING COMPANY c/o

Section 1. <u>EARTHGRAINS</u> is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property. Remediation of this site included removal of the underground storage tank system and groundwater quality monitoring to evaluate natural attenuation of residual petroleum contamination. Methyl tert butyl ether (MtBE) in groundwater at concentrations above the Wisconsin Administrative Code NR 140 enforcement standard remains at this property, as shown on the attached figure and table. The depth to residual groundwater contamination is about five feet to eight feet below ground surface. Natural attenuation is the approved remedial alternative for the residual groundwater contamination at this property.

Section 3. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

If contaminated materials are excavated in the future, they may be considered a solid waste and must be managed in accordance with all applicable laws.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the

as contained herein can be extinguished. Conditions under which a restriction may be extinguished will be aned in accordance with the site specific standards, rules and laws for this property. If the Department determines ne restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be orded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed apon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 26th day of June, 20 02.

[When appropriate use the following clause]:

[Wildings appropriate	
By signing this document, [he/she] acknowledges that [he/she] is duly authorized to sign this docume	nt on behalf of
By signing this document, (no sne) acidiowices and the	
METZ BAKING CO.	

Signature: Cen & School

Printed Name: FLMIN K. Scitul +7 Pin

Title: VP OF ENGINEERS, EN. & SATETY


Subscribed and sworn to before me this 26-thday of JUNE, 2002


Notary Public, State of MISSOUR


My commission_

This document was drafted by the Wisconsin Department of Commerce.

ATTACHED FIGURES 1,2, &3, TABLES 1 & 2







MONITORING WELL LOCATIONS MAP METZ BAKING COMPANY 918 W. SOMERS ST. MILWAUKEE, WISCONSIN



FIGURE 4

AutoCAD File: 599WORK
Summit Proj. No: 0145-067
Plot Date: 6/8/99
CAD Operator: DLM
Reviewed by: BHB




TABLE 2
Groundwater Laboratory Analytical Results
JAEGER BAKERY
918 West Somers Street
Milwaukee, Wisconsin
Summit Project No. 0145-067

		Ethyl-	į	n-Propyl-	- F	ğ	m- & p-	o-Xylene	Car
	Benzene	benzene	MTBE	benzene	Loluene	IMBs	Aylenes	& Styrene	GKO
3/26/99	<10	425	374	425	25	25	425	425	213
66/9/8	<15	<50	807	<15	<40	<40	<40	<15	463
11/5/99	\Diamond	<10	716	NA	%	~	~	δ.	657
2/25/00	$\overline{\vee}$	7	308	NA	∇	4	∇	∵	147
5/2/00	<0.5	<0.5	184	NA	<0.5	∀	<0.5	NA	122
3/26/99	8	<50	1130	<50	<50	<50	∇	∇	999
66/9/8	<15	<50	872	<15	<40	<40	<40	<15	206
11/5/99	\&	<10	629	NA	%	∞	∞	δ.	362
2/25/00	3.2	<0.5	401	NA	<0.5	∇	<0.5	<0.5	253
5/2/00	1.68	<0.5	239	NA	<0.5	∇	<0.5	NA	264
3/26/99	<10	<25	763	<25	<25	425	∇	∇	381
66/9/8	♡	<10	173	\$	%	%	♡	Ψ	113
11/5/99	<0.15	<0.5	157	NA	<0.4	<0.4	<0.4	<0.15	101
2/25/00	<0.5	<0.5	93.1	NA	<0.5	∇	<0.5	<0.5	<50
5/2/00	<0.5	<0.5	345	NA	<0.5	7	<0.5	NA	149
5/12/00	<0.2	<0.5	<0.3	1.35	<0.5	<0.5	∇	∇	<50
66/9/8	<0.15	<0.5	<0.3	<0.15	<0.4	<0.4	<0.4	<0.15	<50
11/5/99	<0.15	<0.5	<0.3	NA	<0.4	<0.4	<0.4	<0.15	<50
2/25/00	<0.5	<0.5	<0.2	NA	<0.5	∀'	<0.5	<0.5	<50
5/2/00	<0.5	<0.5	<0.2	NA	<0.5	7	<0.5	NA	<50
ES	5	700	09	NE	343	480	620		NE
PAL	0.5	140	12	NE NE	69	96	124		NE NE

Table 1 Groundwater Elevation Data Jaeger Bakery Milwaukee, Wisconsin

Monitoring Well	Date Measured	Top of Casing Elevation	Depth to Groundwater	Groundwater Elevation
MW-1	8/6/99	87.07	4.83	82.24
*	2/25/00		6.98	80.09
	5/2/00		7.77	79.3
MW-2	8/6/99	88.05	5.95	82.1
	2/25/00		5.46	82.59
	5/2/00		5.62	82.43
MW-3	8/6/99	88.77	6.62	82.15
	2/25/00		6.31	82.46
	5/2/00		6.48	82.29
MW-4	8/6/99	84.86	8.8	76.06
	2/25/00		8.88	75.98
	5/2/00		8.62	76.24

Measurements are in feet.

